

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4805	DATE	15. Sep. 2020
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Since molds used to mold reflector mirrors of a rear reflector were improperly handled, some of the reflector mirrors have uneven surfaces.</p> <p>As a result, reflected light may be scattered and fail to conform the Article 38 (Criteria for rear reflectors) of the safety standards.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-SE86J	NMAX125	2015~2017	12,440
2BJ-SED6J	NMAX125	2017~2020	9,509
2BK-SG50J	NMAX150	2017~2020	6,439
2BK-SG42J	XMAX250	2017~2020	6,013
JBK-RG10J	YZF-R25	2014~2017	12,800
	YZF-R25A	2015~2017	3,480
	MT250	2015~2017	5,280
2BK-RG43J	YZF-R25	2017~2020	4,448
	YZF-R25A	2017~2020	4,634
	MT250	2017~2019	3,080
	MT-25A	2019~2020	680
EBL-RH07J	YZF-R3A	2015~2017	3,400
	MT320	2015~2017	1,880
2BL-RH13J	YZF-R3A	2017~2020	2,387
	MT320	2017~2019	1,400
	MT-03A	2019~2020	360
		TOTAL	78,230