

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4804	DATE	Sept.18 2020
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	Since the rear wheel steering lock system of the wheel cranes were improperly programmed, unexpected excessive force may be applied to the drop arm when the rear wheel steering lock is performed. Therefore, the drop arm may be deformed, and the straight traveling stability may be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC016	KR-50H	2016~2019	504	
TOTAL			504	