

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3099	DATE	2020/10/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain A-Class (177 platform), B-Class (247 platform) vehicles with 4-cylinder gasoline engine M282 the oil supply line of the turbocharger might leak.</p> <p>In this case, engine oil might leak from the oil supply line onto the vehicle underbody cover and from there onto the road. This would increase the risk of a crash for other road users. Additionally, it cannot be completely ruled out that leaking engine oil might get in contact with hot components in the engine compartment. Thus, a risk of fire cannot be fully excluded.</p> <p>Local legal regulations in Japan might not be fulfilled.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-177084	A 180	2020	186
5BA-177184	A 180 Sedan		116
5BA-247084	B 180		99
		TOTAL	401