

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4814	DATE	October 1 ,2020
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>(1)With regard to the brakes for the buses, as materials used for plastic pistons in relay valves for parking brakes are inappropriate, the pistons may be hydrolyzed by moisture in the air circuits and damaged by brake air pressure. Consequently, this may potentially lead to air leakage from brake valves, parking brakes being unreleasabe, and brake drag.</p> <p>(2)With regard to the exhaust gas diffusing prevention devices of the buses, due to the improper engine control program to regenerate DPD (Diesel Particulate Defuser), a part of the DPD regeneration fuel may burn in the downstream of DPD and raise the exhaust gas temperature near the urea SCR (Selective Catalytic Reduction). Consequently, the radiant heat may melt the diesel exhaust fluid hoses and other parts, potentially causing diesel exhaust fluid to leak out and nitrogen oxide (NOx) in the exhaust gas to exceed the exhaust gas standard level.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-LV290N1 QKG-LV290N1 QPG-LV290N1	[ERGA]	2015-2017	1,048
2DG-LV290N2 2KG-LV290N2 2PG-LV290N2 2TG-LV290N2		2017-2019	1,174
2DG-LV290N3 2KG-LV290N3 2PG-LV290N3 2TG-LV290N3		2019	307
QDG-LV290Q1 QKG-LV290Q1 QPG-LV290Q1 QRG-LV290Q1		2015-2017	273
2DG-LV290Q2 2KG-LV290Q2 2PG-LV290Q2 2TG-LV290Q2		2017-2019	318

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-LV290Q3 2PG-LV290Q3 2TG-LV290Q3	[ERGA]	2019	74
SKG-LR290J2	[ERGA MIO]	2016-2017	265
2KG-LR290J3		2017-2019	575
2KG-LR290J4		2019	171
2SG-HL2ANBD	[ISUZU ERGA]	2018-2019	11
2SG-HL2ASBD		2018-2019	7
		TOTAL	4,223

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-LV290N1	[ERGA]	2015-2016	16
QPG-LV290Q1		2015	3
		TOTAL	19

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Relay Valve Assembly	8-98292213-0	2017-2019	148
Relay Valve Repair Kit	8-98165977-0	2016-2019	1,267
		TOTAL	1,415