VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Gai-3104	DATE	October 1, 2020
Automobiles PEUGEOT		
(Japanese Importer :	Groupe PSA Japan Co., I	_td.)
On affected vehicles, the bolts securing rear seat cushion to body may lose		
due to insufficient tightening torque. By the stress during driving, the		
frame of the seat cushion may brake at welded portion and in the worst		
cases, the seat cushion may not be fixed to the body and passenger could		
not seat safely.		
	Automobiles PEUGEOT (Japanese Importer: On affected vehicles, the due to insufficient tighte frame of the seat cushion cases, the seat cushion in	Automobiles PEUGEOT (Japanese Importer: Groupe PSA Japan Co., L On affected vehicles, the bolts securing rear seat of due to insufficient tightening torque. By the stream of the seat cushion may brake at welded process, the seat cushion may not be fixed to the bolts.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P845G01	3008	2016 - 2017	258
	TOTAL		258