

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4817	DATE	October 7, 2020
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In some cooling water hoses for agricultural tractors, the cooling water hose and the belt interfere with each other when the belt is stretched because the gap between the hose and the compressor belt is inappropriate. Therefore, if the cooling water hose is continued to be used as it is, the cooling water hose may be damaged and the cooling water may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YT222」	2017~2018	29	
	「YT225」	2017~2018	232	
		2017~2018	38	
	TOTAL		299	