

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3106	DATE	October 7. 2020
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	Some washers used for idle gears that drive oil pumps for agricultural tractors wear early due to improper heat treatment. Therefore, the washer wears and the bush becomes loose, and if it is used as it is, the bush will be damaged and the damaged debris will get caught in the oil pump, and in the worst case, the engine may be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「JD-6110M」	2020	1	
	「JD-6120M」	2020	4	
	「JD-6130M」	2020	9	
	「JD-6135M」	2020	1	
	「JD-6130R」	2020	8	
-	「JD-6155M」	2020	2	
	「JD-6175M」	2020	2	
-	「JD-6195M」	2020	12	
	「JD-6155R」	2020	4	
	「JD-6195R」	2020	1	
	「JD-6215R」	2020	1	
TOTAL			45	