

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4810	DATE	October 8,2020
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Regarding the electric compressor of the A/C, its cover does not have sufficient corrosion resistance, so water may enter the compressor. Therefore when a short circuit occurs inside of the compressor, the EV warning lamp may be illuminated and the motor output of vehicles may be restricted. Also, when the lever is shifted to P range with that condition while vehicles are stopped, the power supply may be shut off and the vehicles may become unable to drive.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	「i-MiEV」	2009~2012	9,563
		2009~2012	9,563