

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3108	Date	October 08, 2020
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In exhaust system, an incorrect catalytic converter may have been installed because of improper production control in the catalytic converter assembly process. Since the exhaust system does not match the engine control unit, particulate matter accumulates inside the catalytic and an indicator light in the instrument cluster may be activated. As a result, the catalytic converter may be damaged and it is possible that the exhaust emissions no longer comply with the type approval.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AWCHZ	Polo 1.0/70kW	MY2019-MY2020	4,148
		Total	4,148