

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |                                                                                                                                                                                                                                                                                                                                                                                                                                          |      |             |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------------|
| CAMPAIGN No.          | 4818                                                                                                                                                                                                                                                                                                                                                                                                                                     | DATE | Oct.15,2020 |
| MANUFACTURER          | DAIHATSU                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |             |
| DESCRIPTION OF DEFECT | In the auto adjusting structure for the clearance between the shoe and the drum of the rear brake, grease is applied insufficiently to the screw surface of the adjuster bolt due to improper control of the grease coating machine during the parts assembly process. If a vehicle with this condition is used over time, the screw surface may get rusty and stuck, possibly resulting in malfunction of the auto adjusting structure. |      |             |

| TYPE       | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| DBA-LA150S | MOVE            | 2017-2018           | 33,757            |
| DBA-LA160S |                 |                     | 8,139             |
| DBA-LA250S | CAST            | 2017-2018           | 21,673            |
| DBA-LA260S |                 |                     | 4,769             |
| DBA-LA360S | Mira e:s        | 2017-2018           | 8,231             |
| DBA-LA600S | TANTO           | 2017-2018           | 62,419            |
| DBA-LA610S |                 |                     | 13,530            |
| DBA-LA700S | WAKE            | 2017-2018           | 14,059            |
| DBA-LA710S |                 |                     | 2,726             |
| DBA-LA800S | MOVE canbus     | 2017-2018           | 37,684            |
| DBA-LA810S |                 |                     | 7,545             |
| HBD-LA700V | HIJET Caddie    | 2017-2018           | 378               |
| HBD-LA710V |                 |                     | 130               |
| DBA-M700S  | Boon            | 2017-2018           | 3,362             |
| DBA-M710S  |                 |                     | 636               |

| TYPE       | COMMERCIAL<br>NAME | MODEL<br>YEAR<br>RECALLED | NUMBER OF<br>VEHICLE |
|------------|--------------------|---------------------------|----------------------|
| DBA-M900S  | THOR               | 2017-2018                 | 11,621               |
| DBA-LA250A | PIXIS JOY          | 2017-2018                 | 3,154                |
| DBA-LA260A |                    |                           | 790                  |
| DBA-LA360A | PIXIS EPOCH        | 2017-2018                 | 1,466                |
| DBA-LA700A | PIXIS MEGA         | 2017-2018                 | 3,397                |
| DBA-LA710A |                    |                           | 690                  |
| DBA-M700A  | PASSO              | 2017-2018                 | 23,633               |
| DBA-M710A  |                    |                           | 4,367                |
| DBA-M900A  | ROOMY/TANK         | 2017-2018                 | 76,217               |
| DBA-LA150F | STELLA             | 2017-2018                 | 2,537                |
| DBA-LA160F |                    |                           | 1,355                |
| DBA-LA360F | PLEO PLUS          | 2017-2018                 | 950                  |
| DBA-LA600F | CHIFFON            | 2017-2018                 | 2,226                |
| DBA-LA610F |                    |                           | 1,063                |
| DBA-M900F  | JUSTY              | 2017-2018                 | 1,074                |
|            |                    | TOTAL                     | 353,578              |