

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|-------------|
| CAMPAIGN No. | 4821 | DATE | Oct.15.2020 |
| MANUFACTURER | TOYOTA | | |
| DESCRIPTION OF DEFECT | In the exhaust brake system of the subject vehicles, due to improper programming of engine ECU to control exhaust brake, the exhaust brake could be inoperative while driving on a descent. In this condition, the required deceleration would not be gained, resulting in noncompliance with the requirement prescribed in “Safety Regulations for Road Vehicles”, Article 12 (requirement of braking system). | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | NOTE |
|------------|--------------------------|---------------------|-------------------|---|
| 2KG-XZB70 | [TOYOTA COASTER] | 2019-2020 | 363 | equipped with N04C-WB engine and automatic transmission |
| 2KG-XZB80 | | 2020 | 2 | |
| 2PG-XZB60V | [TOYOTA COASTER BIG VAN] | 2019-2020 | 16 | |
| 2KG-XZB70M | [HINO LIESSE II] | | 337 | |
| 2KG-XZB80M | | 2020 | 3 | |
| TOTAL | | | 721 | |