

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3109	DATE	October 16, 2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, water pump belt may brake due to the damage made during its installation at engine plant. In the worst case, this may cause lack of engine cooling and finally engine overheat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T9HN02	308	2018	42
ABA-T9WHN02	308	2018	10
TOTAL			52