VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4822	DATE	Oct.20,2020		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	On some wheel cranes, the fastening range of the hose protective material on hydraulic steering circuit hoses has been found to be inappropriate and may result in a risk of local bending load to the hoses. Therefore, with continued use of the hoses in this state, they may be damaged from continuous pressure, hydraulic oil may leak, and the steering operation performance may be hindered.				

TYPE	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLES
WDR-T010	TADANO 「GR-130N-1」		2013-2017	948
WDR-EK05	KOBELCO 「RK130」	2013-2017		57
			TOTAL	1005