

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4823	DATE	Oct.20,2020
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>(1) On some wheel cranes there is inadequate clearance between the engine fuel line piping and the frame such that the fuel line piping may come into contact with the frame due to ignition related vibrations. Therefore, continued use in this condition may result in damage to the fuel pipe, and in the worst case, a leak of fuel.</p> <p>(2) On some wheel cranes there is inadequate clearance between the engine fuel line piping and the frame due to improper assembly and variance in piping. Therefore, continued use of cranes where the fuel pipe and the frame are in contact may result in fuel pipe damage and, in the worst case, a leak of fuel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T014	TADANO 「GR-160N-4」	2017 - 2020	396
YDS-EW08	KOBELCO 「RK160-8」	2017 - 2020	18
		TOTAL	414