## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-3112	DATE	20th Oct 2020	
MANUFACTURE	Triumph Motorcycles Limited			
	(Japanese Importer : Triumph Motorcyces Japan K.K. )			
DESCRIPTION OF				
DEFECT	With repeated steering inputs the main harness wiring may become damaged by contact with the			
	lower lug on the headstock casting. resulting in an engine stall.			

2BL-DGJ900	Thruxton	2018 - 2019	207
	Thruxton R	2018 - 2020	389
		TOTAL	596