

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	4824	DATE	30 October, 2020
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>On the relevant agricultural crawler tractor, the pull force of the coil of the parking brake and sub-transmission valve may be reduced due to inadequate heat resistance of the coil when the tractor is continuously operated.</p> <p>Therefore, in the worst case, the parking brake may not be released or the sub-transmission may not be allowed the shift when the engine is restarted.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-GK13B	「GCR1380」	2018, 2019	44
	「CT1380」	2018, 2019	26
	「TA-C1380」	2018, 2019	11
		TOTAL	81