

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 3 4	DATE	Oct. 29, 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the LED fog lamps, due to improper packaging setting during transportation, when a strong force is applied to the fog lamp, the lens comes off in the fog lamp. Therefore the optical axis may conflict with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-GC27	N I S S A N S E R E N A	2 0 1 9	636
DAA-HC27			491
DAA-GFC27			8,241
DAA-GNC27			210
DAA-HFC27			11,677
DAA-GFNC27			1,700
		TOTAL	22,955