

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4839	DATE	5th - November -2020
MANUFACTURER	Yano Special Vehicle Co., Ltd. 4-2-1 Kaminofukita Shingu Kasuya-Gun, Fukuoka 811-0123 Japan		
DESCRIPTION OF DEFECT	Some spare tire mounting devices mounted between the wheelbases of refrigerated and frozen vehicles have insufficient strength due to improper strength design. Therefore, the mounting device may be cracked due to vibration during traveling, and in the worst case, the spare tire mounting device and the spare tire may fall off, which may hinder other traffic.		
TYPE	COMMERCIAL NAME <input type="checkbox"/>	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FE2ABG	RANGER	2018	1
LKG-FE7JPAA		2010	1
LDG-FG8JPAA		2013	1
BDG-FH1ARXA	PROFIA	2009	1
LKG-FQ1EWBG		2012	2
QKG-FQ1EWBG		2013	3
2RG-FR1AHG		2018	2
2RG-FR1AHJ		2018	3
QKG-FR1APBG		2013	1
2PG-FR1EHG		2017	1
LKG-FR1EXBG		2010~2011	3
QKG-FR1EXBG		2013~2014	7
LKG-FR1EXBJ		2011	1
QKG-FR1EXBJ		2013~2014	3
QPG-FR1EXEG		2014~2017	15
QPG-FR1EXEJ		2014~2017	10
KS-FR1EXWG		2005	1
PK-FR1EXWG		2005	2
BKG-FR1EXYG		2007~2010	7
LKG-FR1EZBG		2011	1
LKG-FR1EZBJ		2010	1
QPG-FR1EZEG		2014	1
QPG-FR1EZEJ		2015	2
BDG-FR1EZYG		2008	4
BKG-FR1EZYG		2009	2
BDG-FR1EZYJ		2008~2009	2
QKG-FS1EWBG		2013	2
LKG-FS1EWBJ		2010	1
QPG-FS1EWEG		2014	1

TYPE	COMMERCIAL NAME□	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FS1EWBJ	PROFIA	2012	1
2RG-FW1AHG		2018	1
2PG-FW1EHJ		2018	1
QKG-FW1EXBJ		2013~2014	9
QPG-FW1EXEG		2016	2
QPG-FW1EXEJ		2014~2016	5
			TOTAL 101