## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3120	DATE	2020/11/5		
MANUFACTURE	Mercedes-Benz AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )				
DESCRIPTION OF DEFECT	On certain G-Class vehicles (463 platform) a hose of the fuel filler pipe might leak.				
DEFECT	In this case, small amounts of fuel might leak during refueling. A contact of potentially leaking fuel with hot components (e.g. exhaust system) is excluded, therefore a risk of fire is excluded as well.				
	Nonetheless, local legal regulations regarding fuel system tightness could not be met.				
	On vehicles with gasoline engine, the legal emission limits for fuel evaporation could b exceeded.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-463349	G350d	2019	438
		2020	153
ABA-463260	G550	2019	125
3BA-463260	G550	2020	14
ABA-463276	Mercedes-AMG G63	2019	648
		2020	115
		TOTAL	1,493