

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3121	DATE	2020/11/5
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain GLB-class vehicles (X247 platform) the rear spoiler located above the tailgate might have been manufactured outside specifications. The upper shell of the rear spoiler might not have been welded at all or welded incorrectly to the base part.</p> <p>In case of a missing welding, it cannot be ensured that the upper shell is sufficiently connected to the base part.</p> <p>Should the rear spoiler have been welded incorrectly, the weld could break in case of a collision of the rear spoiler with the vehicle roof when opening the tailgate of the vehicle.</p> <p>In both cases, it cannot be ruled out that parts of the rear spoiler might detach while driving. This would increase the risk of a crash or injury for other road users.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-247612M	GLB200d	2020	68
5BA-247647M	GLB250 4MATIC		67
		TOTAL	135