

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3122	DATE	2020/11/5
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain AMG GT 4-doors Coupe (290 platform) vehicles with 6-cylinder gasoline-engine (M256) the installed ignition coils might not meet the specification.</p> <p>Subsequently, an ignition coil could no longer build up ignition voltage, which would lead to misfiring on the affected cylinder.</p> <p>In this case, the limp home mode with reduced engine power would be activated and the malfunction indicator lamp (MIL) would be illuminated. Furthermore, local legal requirements regarding emission values might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4AA-290659	Mercedes-AMG GT43 4MATIC+	2020	2
4AA-290661	Mercedes-AMG GT53 4MATIC+		3
		TOTAL	5