

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	GAI-3118	DATE	November 9, 2020
MANUFACTURE	Bombardier Recreational Products Inc. BRP Japan Ltd.		
DESCRIPTION OF DEFECT	One or more wheel nuts may crack resulting in a reduced clamping force. This could eventually affect the integrity of the wheel assembly and the vehicle's behavior. This may increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF	Can-Am Ryker 600	2019	6
2FG	Can-Am Ryker 900	2019	17
2GG	Can-Am Ryker 900 Rally	2019	12
		TOTAL	35

## 【記入例】

### VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic / Import Vehicles
CAMPAIGN No.	GAI-	DATE	July 21, 2005
MANUFACTURE			
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順で<b>リコール届出年月日</b>を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		<p>製作年のみの記載。</p> <p>2005－2006</p>	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数