

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3119	DATE	November 9, 2020
MANUFACTURE	Bombardier Recreational Products Inc. BRP Japan Ltd.		
DESCRIPTION OF DEFECT	The front wheels assembly may not have been performed properly (torque application and installation of the red locking clip). In some situations, this could result in a wheel loss, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF	Can-Am Ryker 600	2020	8
2GG	Can-Am Ryker 900 Rally	2020	15
		TOTAL	23

## 【記入例】

### VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic / Import Vehicles
CAMPAIGN No.	GAI-	DATE	July 21, 2005
MANUFACTURE			
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順で<b>リコール届出年月日</b>を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		<p>製作年のみの記載。</p> <p>2005－2006</p>	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数