

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN
Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4849	DATE	2020/11/24
MANUFACTURER	HANTA MACHINERY CO. LTD.		
DESCRIPTION OF DEFECT	As for license plate rump of asphalt finishers, in accordance with revision of safety standard, there are license plate rumps which are still complied with the previous standard. Therefore, it is not conform to Article 36 in current safety standard which is the standard of license plate rump.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-F45W5	「45 J」	2020~2020	3
YDN-A45WD	「45 J」	2020~2020	4
YDN-F40W5	「1741W」	2020~2020	1
		TOTAL	8

(日本産業規格A列4番)

備考 不具合箇所が複数ある場合であって対象車が異なる場合には、それを区別して記載すること。