

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4868	DATE	November 26,2020
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to an improper assembly of the parking brake operating shaft at the rear brake calipers, rust-proof coating on the shaft may come off. This may cause rust to form on the shaft when water enters through the sealing portion and the shaft gets wet.</p> <p>If use is continued in that state, rust on the shaft may progress to the inside of the caliper and block the shaft rotation, which may reduce the parking brake force. In the worst case scenario, there is a risk that the parked vehicles may start moving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2016	3,007
DBA-CV2W		2016	308
DBA-CV5W		2016	355
DLA-GG2W	「OUTLANDER PHEV」	2016	2,362
DBA-GF7W	「OUTLANDER」	2016	450
DBA-GF8W		2016	715
DBA-GA4W	「RVR」	2016	359
		TOTAL	7,556

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
REAR BRAKE CALIPER KIT LH	4605B649	2016	34
REAR BRAKE CALIPER KIT RH	4605B650	2016	35