VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai - 3129	DATE	2020.11.27	
MANUFACTURER	StreetScooter GmbH (Japanese Importer : StreetScooter Japan K.K.)			
DESCRIPTION OF DEFECT	The tightening torque of the bolts that fix the drive motor fixing subframe to the main frame is improperly set, so the tightening torque may be insufficient. Therefore, the bolt loosens due to running vibration and abnormal noise is generated, If the bolts were used as it are, in the worst case, the drive motor may fall off and the running may become impossible.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-D17SMG180	StreetScooter D17	2019	361
		TOTAL	361