

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3130	DATE	Nov.27.2021
MANUFACTURE	Putzmeister Concrete Pumps GmbH (Japanese Importer : Putzmeister Japan CO.LTD)		
DESCRIPTION OF DEFECT	In the propeller shaft, the tightening bolts removed in the reassembly process when the concrete pump device was installed were reused, so the bolts may loosen during running, causing abnormal noise and vehicle body vibration. If it is used continuously as it is, it may become impossible to drive, and in the worst case, the propeller shaft may fall off and interfere with other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	BSF38-5.16H Concrete pump	2019	2 4
UNKNOWN	BSF28-4.16H Concrete pump	2019	2
		TOTAL	2 6