

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4858	DATE	Dec 4, 2020
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Since the work of removing the air remaining in the brake circuit in the manufacturing process of the excavator loader is inappropriate, the air may not be completely removed and may remain. Therefore, if high-speed and long-distance driving is performed with extremely few brake operations, the remaining air expands as the temperature of the axle rises and pushes the brake disc, which may lead to driving while dragging the brake.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-WA137	「WA200-8」	2019-2020	113
YDR-WA136	「WA270-8」	2019-2020	75
YDR-WA135	「WA320-8」	2019-2020	20
TOTAL			208