

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3140	DATE	2020/12/10
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain GLC (253 platform) the wiring harness of the steering control unit might not have been manufactured according to specification.</p> <p>In this case, the wiring harness of the steering control unit might have been damaged in the production process, which could lead to a moisture ingress into the wiring harness. In consequence, it cannot be excluded that moisture might also enter into the control unit. This might result in a loss of the electric power steering support and therefore increase the risk of a crash.</p> <p>Furthermore, a short circuit of the damaged wiring harness and in this connection a potential risk of fire cannot be fully ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-253315	GLC220d 4MATIC coupe	2020	4
3DA-253915	GLC220d 4MATIC		2
3DA-253915C			1
4BA-253364	Mercedes AMG GLC43 4MATIC coupe		1
		TOTAL	8