

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3141	DATE	2020/12/10
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain A-Class (177 platform) vehicles the screw connection of the control unit box might not meet the specification. Should this screw connection not meet the specification, the control unit box could become loose over time, leading to vibrations on the control unit box. The vibration could lead to excessive mechanical stress and damage the fuses in the control unit box causing contact interruption and preventing the availability of certain vehicle functions including engine operation, steering power assistance, ESP system, and active brake assistance, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-177012	A200d	2019	2
		TOTAL	2