

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3145	DATE	December 14th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate setting of the assembling tool, the bolts for assembling the front seat belt on driver and passenger's side may not have been sufficiently tightened. In the event of a crash, the seat belt might detach from vehicle body, which could affect the restraint capability and increase the risk of injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-UZ20	「BMW X3 xDrive20d」	2020	14
LDA-TX30	「BMW X3 M40d」	2020	3
		TOTAL	17