

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4 8 6 4	DATE	Dec. 15. 2020
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p>Cam chain tensioners that adjust the tension of the cam chain of an engine are damaged at an early stage due to improper control during manufacturing. Therefore, an abnormal noise is generated from the cam chain, and if the cam chain is used as it is, the cam timing may shift, and in the worst case, the engine may stop during running.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-EX400G	Ninja 400	2020	607	
	Z400	2020	73	
2BK-EX250P	Ninja 250	2020	197	
	Z250	2020	78	
2BK-ZX250E	Ninja ZX-25R	2020	1108	
	Ninja ZX-25R SE	2020	2594	
TOTAL			4657	