

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4836	DATE	Dec. 16 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty trucks, grease is not applied to the slide pins of the front wheel brake calipers. If the vehicle continues to be used in this condition, the outer pads become unable to fully return and cause significant wear. In the worst case, the outer pads may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-FBA20	「FUSO CANTER」	2017~2019	9,638
TPG-FDA00		2017~2019	811
TPG-FDA20		2017~2019	543
TPG-FDA40		2017~2019	121
TPG-FEA20		2017~2019	1,499
TPG-FEB20		2017~2019	421
TPG-FGA20		2017~2019	412
TRG-FBA20		2017~2019	101
TRG-FDA00		2017~2017	4
TRG-FDA20		2017	1
TRG-FDA40		2019	1
TRG-FEA20		2017~2019	54
TRG-FEB20		2017~2019	48
TRG-FGA20		2017~2018	5
2RG-FBA20		2019~2020	2,261
2RG-FDA20		2019~2020	215
2RG-FDA40		2019~2020	29
2RG-FEA20		2019~2020	429
2RG-FEB20		2019~2020	121
2RG-FGA20		2019~2020	112
2TG-FDA00	2019~2020	231	
TRG-FBA2W	「ATLAS」	2017~2019	24
TRG-FDA2W		2017~2019	89
TRG-FDA4W		2017~2019	11
TRG-FEA2W		2017~2019	78
TRG-FEB2W		2017~2019	49
TRG-FGA2W		2017~2019	41
2RG-FBA2W		2019~2020	5
2RG-FDA2W		2019~2020	25
2RG-FDA4W		2019~2020	4

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-FEA2W	「ATLAS」	2019~2020	25	
2RG-FEB2W		2019~2020	12	
2RG-FGA2W		2019~2020	11	
TPG-FBA2Y	「Kazet」	2017~2018	6	
TPG-FDA2Y		2018~2019	3	
TPG-FEA2Y		2017~2018	2	
TRG-FBA2Y		2017~2018	7	
TRG-FDA2Y		2017~2019	3	
TRG-FDA4Y		2017~2019	5	
TRG-FEA2Y		2017~2018	3	
TPG-FGA2Y		2018~2019	5	
TRG-FGA2Y		2017~2019	10	
2RG-FBA2Y		2019~2020	3	
2RG-FGA2Y		2019~2020	4	
		TOTAL	17,482	