

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4854	DATE	December 16, 2020
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	As the material of the packing for the positive pole inside the battery is inappropriate, excessive corrosion may be generated and deposited in the pole portion. Therefore, the pole is raised by corrosion and may be broken. Battery power to the truck may be cut off, then the truck may not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-SB1L	FB18PSXIII	2018	1
ZAF-SB2L	FB25PSXIII	2018	7
		TOTAL	8