

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|--|------|-------------------|
| CAMPAIGN No. | 4855 | DATE | December 16, 2020 |
| MANUFACTURE | SUMITOMO NACCO FORKLIFT CO., LTD. (Japan) | | |
| DESCRIPTION OF DEFECT | As selecting the material of the hose for supplying gasoline to the engine is inappropriate, there may be early crack on the hose. Therefore, the fuel may leak from the crack if the truck continues to be used as it is. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|--|---------------------|-------------------|
| EBT-G1M | FG20PXII FG20PXIII | 2014 - 2015 | 2 |
| EBT-G2L | FG25PXII FG25PXIII | 2014 - 2015 | 2 |
| EBT-G2M | FG25PXII FG25PXIII | 2014 - 2015 | 2 |
| EBT-G3H | FT30PXII FG30PXIII FG35PXII FG35PXIII | 2014 - 2019 | 5 |
| EBT-SG1K | FG09PXII FG10PXII FG14PXII FG15PXII FG18PXII FG20PXII FG09PXIII FG10PXIII FG14PXIII FG15PXIII FG18PXIII FG20PXIII | 2014 - 2020 | 228 |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|---|---------------------|-------------------|
| EBT-SG1KT | FT09PXII FT10PXII FT15PXII FT18PXII FT20PXII FT10PXIII FT14PXIII FT15PXIII FT18PXIII FT20PXIII | 2014 – 2020 | 152 |
| EBT-SG2J | FG20PXII FG20PXIII FG25PXII FG25PXIII | 2015 – 2020 | 76 |
| EBT-SG2JT | FT20PXII FT20PXIII FT25PXII FT25PXIII | 2014 – 2020 | 81 |
| SG3B | FG30PXIII FG35PXII FG35PXIII | 2016 – 2019 | 5 |
| SG3BT | FT30PXII FT30PXIII FT35PXIII | 2016 – 2020 | 4 |
| | | TOTAL | 557 |