

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4856	DATE	December 16, 2020
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	As the internal structure of the exhaust vertical tailpipe is inappropriate, the exhaust pressure exceeds the notification value of the device type supplier of carbon monoxide divergence prevention device. When the exhaust vertical tailpipe is mounted on the truck, the exhaust outlet direction of the DOC muffler that is carbon monoxide divergence prevention device is modified in a direction different from the notification of the type device supplier. Therefore, it may not conform to the standard value of the emission regulation classification, 2014.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-D3K	FD30PXIII FD35PXIII	2015 ~ 2018	11
YDN-SD2G	FD20PXIII FD25PXIII	2015 ~ 2020	13
SD3B	FD30PXIII FD35PXIII	2018 ~ 2020	3
		TOTAL	27