

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4869	DATE	December 17, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>The DC-DC converter for the power control unit may, because the elements on the circuit for regulating the supply voltage to the battery have faults attributable to inadequate manufacturing control, shift to the fail-safe mode after starting the cold engine and stop the electrical supply to the battery. Should this happen, the battery would be undercharged, when the warning light and indicator would come on and the vehicle could be disabled.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-ZE4	「INSIGHT」	2019-2020	2,100
		TOTAL	2,100