

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3144	DATE	December 18th, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The oil filler cap was not installed according to specification due to an incorrect assembly machine setting. In this condition, the engine oil may leak from the engine cylinder head cover.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-YU15T	MINI Cooper SE Crossover A4	2020	7
		TOTAL	7