

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3151	DATE	23rd Dec 2020
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	Some Rocket III models with anti lock brakes (ABS) were manufactured using a rear brake system fluid fill process that may not meet quality standards. A small amount of air may therefore remain in the ABS modulator. Degradation of the rear brake efficiency, if unattended, can increase the risk of a crash.		

2BL-YJJ2500	Rocket3R	2020	147
	Rocket TFC	2020	15
		TOTAL	162