

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4872	DATE	January 8, 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	As for the batteries of electric forklifts, the material of pole packing which supports the positive electrode pole is inappropriate. This may cause the positive electrode pole to corrode. The continuous use can damage the positive electrode pole and lead to conduction failure. In the worst case, the vehicle may not be able to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M282K	「FB20」 「FB25」	2018	7
ZAF-SM236K	「FB15」	2018	1
		TOTAL	8

### Models of vehicles that may be used as service parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M042	—	2006	1
M190	—	2003	1
		TOTAL	2

### Pedals that were shipped as service parts and unknown to which units were used

PARTS NAME	PARTS NUMBER	SHIPPING YEAR	NUMBER OF PARTS
BATTERY A.	37A-2E6-1020	2018	2
BATTERY A.	37A-2D6-1020	2018	1
		TOTAL	3