

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3157	DATE	January 18th, 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Increased wear of the timing chain of 4-cylinder diesel engine can lead to elongation of the timing chain. The chain elongation can cause chain breakage or engine damage due to incorrect valve timing. In the worst case, the engine may stop during driving and cannot be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-XD20F	MINI Cooper D Crossover	2014 - 2015	1,902
LDA-XD20A	MINI Cooper D Crossover A4		1,094
LDA-ZB20	MINI Cooper SD Crossover		1,759
LDA-RS20	MINI Cooper D Paceman		190
		TOTAL	4,945