

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 7 7	DATE	Jan. 21. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Regarding the front side member, due to a malfunction of the press machine, the side member panel may be cracked.</p> <p>Therefore, the strength of the side member becomes low, and the strength of the vehicle body for securing a passenger space in the case of a front vehicle collision is insufficient, and in worst case, the passenger may be injured.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-ZE1	N I S S A N L E A F	2 0 2 0	31
		TOTAL	31