

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4880	DATE	January 28 ,2021
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the detection instrument (photoelectric device) of the bus entrance door opening/closing system, misdetection in the photoelectric device might occur and cause the bus door unable to open or close because of the insufficient examination on the impact of external factors, such as water adhesion and ambient light, towards the photoelectric tube.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-LV290N3 2KG-LV290N3 2PG-LV290N3 2RG-LV290N3 2TG-LV290N3	[ERGA]	2019-2020	752
2KG-LV290Q3 2PG-LV290Q3 2RG-LV290Q3 2TG-LV290Q3		2019-2020	172
2KG-LR290J4	[ERGA MIO]	2019-2020	263
		TOTAL	1,187