

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3186	DATE	Mar 04 2021
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	The driver airbag (DAB) emblem may have become loose or detached which may result in either the emblem or retainers, or both, not remaining attached to the DAB cover during DAB deployment. A loose or detached emblem or emblem retainer can become a potential projectile during a crash with DAB deployment, which increases the risk of occupant injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RT38	「Grand Voyager」	2008-2010	468
ABA-KA37	「Nitro」	2007-2011	1,615
		TOTAL	2,083