

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3184	DATE	March 4, 2021
MANUFACTURE	DS Automobiles (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, adhesive applied to fuel tank may be insufficient at manufacturing. This may cause fuel leakage form the portion where the adhesive is insufficient.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-D34HN05	DS 3 Crossback	2019	251
	TOTAL		251