

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	4 9 0 6	DATE	March. 8. 2021
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the urea SCR device of a rotary snowplow, Some urea hoses come into contact with high temperature parts such as exhaust pipes due to improper arrangement instructions. Therefore, if the hose is damaged and urea leaks, the urea SCR device may not operate normally and may not comply with the standard of Article 31 of the safety standard (device for preventing emission of harmful gas, etc.).</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03F	「HTR308A」	2018~2021 R03F-0002~ R03F-0207	195
TOTAL			195

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.