VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

CAMPAIGN No.	Gai-3182	DATE	11/March/2020
MANUFACTURER	Automobiles Volvo Car Corporation		
	(Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo Cars investigation have identified a problem regarding the		
	front seat belt fastening, mounted on the outboard side of the		
	front seat. The front seat belt fastening cable may over time		
	suffer from reduced strength under certain circumstances. This		
	may lead to insufficient support to the front seat belt function.		
	COMMERCIAL	MODEL	NUMBER OF
TYPE	NAME	YEAR	VEHICLE
		RECALLED	
VOLVO	[S80]	2007-2015	1,322
	[S60]	2011-2018	8,743
	[\\70]	2008-2016	10,757
	[XC70]	2008-2016	1,977
	[V60]	2011-2018	20,869
	[XC60]	2010-2017	11,302
VOLVO	[V60CC]	2016-2018	2,575
		TOTAL	57,545