

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4919	DATE	Mar.31.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the alloy wheel of the subject vehicles, due to the improper control of the manufacturing process, the oversea specification alloy wheels which do not have the vehicle indication marking were installed to some vehicles. In this condition, the subject vehicles may not meet a certain requirement prescribed in “Safety Regulations for Road Vehicles”, Article 9 (Standards for Running Device).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6BA-MXAA54	[RAV4]	2021	807	Adventure offroad package
		TOTAL	807	