

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4914	DATE	March 31, 2021
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	In the internal combustion forklift truck equipped with a pneumatic rubber tire, the setting of the rear tire is inappropriate, so that the load on the rear tire may exceed the load capacity of the tire. Therefore, if the forklift truck continue to be used as it is, the tire may puncture, then the truck may not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-D4L	FD50PXII	2015 ~ 2016	4
YDN-D4P	FD50PXIII	2019	1
		TOTAL	5