

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4949	DATE	May 13, 2021
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	In the said garbage compactor, the strength of installing brackets which connect the body and the dumping mechanism may not be sufficient due to inappropriate quality evaluations. Therefore, lashing bolts of the bracket may be broken by unexpected high stresses of the impact when dumping the body at the maximum angle and the body may be separated from the dumping mechanism, then the body may topple backward in the worst case.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	2DG-FC2ABA	HINO RANGER	2020	2
	2DG-GC2ABA		2019	1
	2KG-FC2ABA		2018-2020	22
	2KG-FD2ABA		2018-2020	2
	2KG-FE2ABA		2018-2020	4
	2KG-FJ2ABA		2019	1
	2KG-GC2ABA		2020	4
	2KG-GD2ABA		2019	1
	2PG-FE2ABA		2019	1
ISUZU	2PG-FRR90S2	FORWARD	2018-2020	5
	2PG-FSR90S2		2019	1
	2RG-FRR90S1		2019-2020	5
	2RG-FRR90S2		2018-2020	8
	2RG-FSR90S2		2018-2020	6
MITSUBISHI	2KG-FK61F	FUSO FIGHTER	2018-2019	5
	2KG-FK62F		2020	1
	2KG-FK71F		2018	2
	2KG-FK72F		2020	1
	2KG-FK72FY		2020	1
	2PG-FK72N		2020	2
UD TRUCKS	2PG-BRR90S2	CONDOR	2019	1
	2RG-BRR90S2		2019	1
			TOTAL	77

(日本産業規格A列4番)